G. R. S. 59]

GENERAL AND REVENUE SECRETARIAT.

1906

(Miscl.)

File No. 270.

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Repairs to the Dwajastamba of the Sri Srikanteswaraswami de at Nanjangud

PREVIOUS REFERENCES	LATER REFERENCES
	149 of 08
	389 of 11

MUZRAI SECRETARIAT.

OFFICE NOTE.

File No.

Subject.

Repairs to the Dhwajastambha in the temple of the Sri Srikanteswara Swami at Nanjangud.

From

The Chief Engineer of Mysore

No. 8358 Dated 13th December 1906.

During the inspection of the Sri Srikanteswara Swami temple at Nanjangud by the Muzrai Secretary in June last, he observed that the Dhwajastambha in the temple was a little out of the perpendicular. The Deputy Commissioner was requested to make arrangements ~~that should be made~~ for a careful examination of the Dhwaja-Stambha by the local Assistant Engineer of the P. W. D. ~~for whose report should be made to the Chief Engineer~~.

The Chief Engineer was also

File No. of Muzrai Secretariat.

requested to direct the Assistant Engineer at Nanjangud to inspect and report together & Submit a with an Estimate for the work as to what was required to be done to the Dhwajastambha at an early date.

The Chief Engineer forwards the report of the Assistant Engineer, Nanjangud dt., wherein he states that the bottom of the Dhwajastambha has been rotten owing to the rain water running inside the wood through crevices in the copper sheets enclosed outside. It is further stated that on enquiry made in the District Forest Officers of Mysore and Kadur, Honne wood of 46 feet in height is not available in their Districts and that the Contractor of Malabar promises to supply this pole, if the Estimate is sanctioned. The Chief Engineer forwards for sanction an Estimate for Rs. 500/-. This includes a sum of Rs 96/- for the necessary religious Ceremonies &c.

17/12/06

15/12/06

Muz 8A]

Muzrai Secretariat. | File No. of 190

Muzrai Secretary's remarks:—

The Dhwajasthambha has become rotten at the bottom and has become bent I have seen it Its entire removal and replacement by a new post seem very urgently required The estimate received for Rs 500/- may therefore, it is submitted, be sanctioned, the charge being debited to the savings of the institution. The work may be ordered to be executed with great care by the Public Works Deptt 267 Submitted to the 2nd Councillor.

19. 12 1906.

This was shown to me on the occasion of my recent visit to Kanjangad - The Estimate may be sanctioned & the work ordered to be done carefully

Draft

GPB—3,000—22-6 06

File No. of 190 | Muzrai Secretariat.

Submitted

The amount of the Estimate received from the D.C. yesterday is Rs 290, but the one received from the Chief Engineer which was received back from the II on duly sanctioned was for Rs 500. Orders have not yet been drafted Solicits instructions

ks
20/12/06

A
ks

No. 227 D/12-7-06

[illegible] Department.
[illegible]

Draft
subd to the 2nd for appl
[initials] 10/7/06

From,
[illegible]
Secretary to Government,
[illegible]

To,
[illegible]
[illegible],

Sir,

[illegible] temple [illegible] out of the perpendicular. This has [illegible] request [illegible] close of the [illegible], which is now going on, for a careful examination of the [illegible] are and extent of the damage, [illegible] by the local Assistant Engineer of the P.W.D. for whose services application will be made to [illegible] should, if possible, be [illegible] roof which supports the [illegible]stamba, to some extent, but the covering the [illegible] with [illegible] religious ceremonies at a small cost [illegible] time of the [illegible].

A detailed report should be [illegible] on the subject together with an estimate [illegible] enable [illegible] the P.W.D. of remedying the existing defects.

I have the honour to be,
Sir,
Your most obedient servant
[signature]
[illegible] Department.

88/10.7.06
[initials] 10/7/06

No. 228 D/12-7-06.
Copy to Ch: Engr., with the request that the Asst Engr at Nanjangud may be directed ~~to request~~ inspect & report together with an estimate as to what is reqd to be done to the Dhwajastamba at an early date.
Draft
By order
[initials] 10/7/06
[signature]
Secretary Deptt

MUSEUM
4973

Rpts
ks
19/10/06

1906-07.

From

To

Dated

Despatched

Received

General No. /
No.

Enclosure No.

Submitted for
information
ks
20/10/06 Secy-File
20/10/06
ks

Deputy Commissioner's Office
Bezwada District

No. 127 Dated Bezwada 15th Oct. '66

To
L. Ananthacharlu Esq: B.A.
Secretary to the Government
of Bezwada Bezwada

Sir,

In reply to your letter No: 227 dated the 19th July 1866 calling for the submission of a detailed report together with an estimate of the probable cost of remedying the existing defects of the Dhurga Jasthambha of the Sri Sri Sri Venu Gopala Swami Devasthanam at Vijayawada, I have the honour to state that the Assistant Executive Engineer, Nuzvid Division had written to me to submit the report which had to be returned to him for a detailed report together with an estimate called for in the letter cited above.

2. On receipt of the Assistant Commissioner's further report, it will be submitted to you.

I have the honour to be,
Sir,
your most obedient humble servant

Deputy Commissioner
Bezwada

1906

Ref 1983

From The Chief Engineer of Mysore

To The Secretary to the Government of Mysore, Muzrai Department.

Dated Bangalore 19th October '06.

Despatched

Received

General No. 6944

No.

Enclosure No.

Stating that the Estimate called for for replacing the dvajastambha of the Sri Srikanteswara Swami Temple at Nanjangud will be transmitted on its receipt from the Executive Engineer, Mysore Dn.

Submit for information

20/10/06

File for the present

20/10/06

20/10/06

Docket no. 669 dated 20th September 1906 from the Executive Engineer, Mysore Division, to the Superintending Engineer, Western Circle.

With reference to Superintending Engineer's docket no. 3438 of the 12th instno, calling for an estimate for what is required to the Dvajastambha of the Sri Srikanteswara Swami Temple at Nanjangud, has the honour to report that the Assistant Engineer inspected the Dvajastambha and found it necessary to be replaced by a new one altogether, the bottom portion of the Dvajastambha being rotten. He has also submitted an estimate for the same A Home wood pole of 46' in length is required for its renewal. The District Forest Officer, Mysore, was Consulted and a pole of this length is not available in the Mysore District Forests. The District Forest Officer, Kadur District, has therefore been addressed if a pole of this length can be had there and what its cost will be.

The Estimate will be submitted on receipt of his reply.

No 6944 of 19th October 1906.

Copy of above forwarded to the Secretary to the Government of His Highness the Maharaja of Mysore, Mungrai Department, with reference to his no. 228 of 12th July last for information.

2. The Estimate promised will be forwarded on receipt.

Bernard D Cunn Lieut, R.E.,

Deputy Chief Engineer of Mysore

Refer (illegible)

E1

19/12/06

~~1907~~ 1906-07

FROM
Sr. Kandaraj Urs Esq B.A.
Deputy Commissioner
To Mysore District
L. Anantasawmi Rao Esq B.A
Secy: to Govt- Judgrai Deptt
Dated
Despatched 17th Decr 1906.
Received
General No.
No.

Enclosure No. one file

Submits copy of an estimate amounting to Rs 2907- for repairing the Dhwajastambha in the Sri Srikanteswara Swamis temple at Nan-jangud -

No 236
/ file

Deputy Commissioner's Office
Mysore District
Dated Mysore 17th December 1906

To

L. Anantasami Rao Esq B.A
Secretary to the Government of His
Highness the Maharaja of Mysore,
Muzrai Department, Bangalore

Sir,

As called for in your letter No 227 dated 9th July 1906, I have the honor to submit herewith for favour of orders a copy of an estimate amounting to Rs 290/- for repairing the Dhwaja Stamba in the Sri Srikanteswara Swami temple at Nanjangud and to state that the original Estimate is reported to have been submitted by the Assistant Engineer, Nanjangud Range, to the Executive Engineer, Mysore Division.

The Amildar in his report, received with the accompanying yadi

No

No $\frac{732}{444}$ dated the 6th December 1906

from the Nanjangud Sub Divisional Officer States that the Dhwajastambha is in a dangerous condition and repairs are urgently needed thereto.

I have the honor to be,

Sir,

your most obedient Servant

[signature]

for Deputy Commissioner

Mysore District.

13.0

MYSORE GOVERNMENT
3103
ARCHAEOLOGICAL SECTION

27/12/06

~~1899~~ 1906-07

FROM
M. Kanakaraj Urs Esq B.A.
Deputy Commissioner,
Tumkur District.

To
[illegible] Esq B.A.
[illegible]

Dated [illegible]

Despatched [illegible] Dec 1906.

Received 24

General No. 2[illegible]3

No.

Enclosure No. 2

Submits another report from the Amildar of the Ranjangud Taluk re repairs to Dhwajastamba of the Sri Srikanteswara Swami temple.

No 2263/ar 2 Deputy Commissioner's office
Mysore District
Dated Mysore 22nd Decr 06

To

L. Anantasammi Rao Esq B.A.
Secretary to the Government of
Mysore Municipal Department.

Sir,

In continuation of this office letter no: 238 dated 17th December 1906 I have the honor to submit herewith report no: 163/294 dated the 28th Novr 1906 received from the Amildar of the Nanjangud Taluk requesting that the Dhwajastambha of the Sri Sri Kanteswara Swami temple at Nanjangud may be ordered to be repaired early as it is in a dangerous condition, and to request that the P. W. D. may be requested to take up the work on hand at an early date -

I have the honor to be,
Sir,
your most obedient servant,

[illegible]
Deputy Commissioner
Mysore District

B.d

SUPERINTENDING ENGINEER'S OFFICE
REG'D No 4837
NOV. 21-1906
WESTERN CIRCLE 1906

SECRETARIAT 10054

From The Executive Engineer
Mysore City Division

To The Superintending Engineer
Western Circle

Dated 12th November/06
Despatched 19
Received
General No. 815
No.
Enclosure No. 1st Estate

Superintending Engineer's No. 3638 of 23-7-06 forwarding copy of letter No 228 of 12-7-06 from the Amzari Secretary on the Condition of the Dhwajastamba in the temple of Sri Srikantes-wara Swamy at Nanjangud

In Continuation with this office No 669 of 20.9.06 Submitting an ad interim report on the above, has the honor to state that the under signed inspected the Dhwajastambha on the 5th instant and found the bottom portion of it rotten. It is necessary to replace it by a new one. An

Thro' the Chief Engineer of Mysore

No 5839

Forwarded to the Amzary Secretary to the Govt of Mysore for favor of disposal.

Executive Engineer,
in Charge of Sfty. Engrs. office
Western Circle

Bangalore
29th November
1906

No 8358 D/13.12.06.

Passed on to the Secy to Govt, Amzari dept in continuation of this office No. 6976 of the 19th October last.

W. W. Hudleston
Chief Engineer
of Mysore

Bangalore
13.12.06

Refers
14/12/06

amounting to Rs 500/- is enclosed with a report the work proposed to be carried out.

2- The Stambha is 46' long and the undersigned was informed by the Agnikka and other temple authorities that the new post should be of the same height and that it should not be made up of pieces (Iron or armoured posts cannot be used according to their statement for Dhwajstambha). On enquiry, the district forest officers of Cuppone and Kadur inform that such long poles of Stonne or Jambé wood are not available in their districts but that Kratti can be had this wood not very soon and so, it is not advisable to use it. From enquiry it is learnt that Stonne wood poles of the required dimensions can be had in the Malabar forests and it is proposed to get one from there. A Sum of Rs 100/- has been entered in the Estimate for cutting and Carting it from the interior of the forest. A Contractor for carting timber from Malabar promises to supply this pole. If the Estimate be Sanctioned, arrangements will be made for getting a pole and fixing the post with needful repairs to roofs &c.

3- A lump Sum of Rs 96/- is also allowed for the needful religious ceremonies. This amount, it is believed will suffice for the same.

Camp Bedgade

W. Richardson.
Executive Engineer
Cuppone Division

Murzai

Read: -

No 835-8 Dy 13th December 1906 from the Chief Engineer of Mysore forwarding for sanction an Estimate amounting to Rs. 500/- for the replacement of the Dhwajastambha in the temple of Sri Srikanteswara Swami temple at Nanjangud.

And, Letter No 238 Dy 17th December 1906 from the Deputy Commissioner of the Mysore District submitting for sanction an estimate for Rs 290/- for the same work - " -

No 3288-90 Ex 1/6 Order thereon No - " -

141 Dy 24/12/06 During the inspection of the Sri Srikanteswara Swami temple at Nanjangud by the Murzai Secretary in June last

~~he~~ observed that the Dhwaja-
Stambha in the temple was a
little out of the perpendicular
The Deputy Commissioner
was requested to make
arrangements for a careful
examination of the Dhwaja
Stambha by the Local Assistant
Engineer of the P. W. D. The
Engineer reports that the
Dhwajastambha has become
rotten at the bottom owing
to the rain water running
inside the wood through the
crevices in the copper sheets
enclosing ~~outside~~ the pole,
and that its entire removal
and replacement by a new
seem very necessary.
Chief Engineer forwards

for sanction an Estimate for 500/- for the replacement of the Dhwajastambha ~~and~~ which also ~~for~~ includes the cost of the necessary religious ceremonies &c

2. Under these Circumstances the Government are pleased to sanction the larger Estimate for Rs 500/-, the charge being debited to the Savings of the Sri Srikanteswara Swami Temple at Nanjangud.

2. The work ~~may~~ should be executed with great care by the P.W.D.

3. The Comptroller is requested to place the Sanctd amount of Rs. 500/- at the disposal of the P.W.D.

(2nd cis under) 21/10/06

21/12/06 Secretary.

To, The Chief Engineer with the Sanctd Estimate.
4 Comptroller, Mysore Govt
4 D.C. Mysore Dt. etc

Mar I A]

190

From The Secretary
Mysore Depart,

To The Deputy Commissioner
Mysore Distt.

Dated

Despatched 16. 1. 07

Received

General No. 342
No

Enclosure No. 2

With reference to his Docket No 2532/22 December 1906, has the honor to state that ~~that~~ an Estimate for Rs 500/- for the replacement of the Dhwajastambha in the Sri Sankareswara Swami temple at Nanjangud was sanctioned in Govt Pro: No 3288-90/24 December 1906 and forwarded to the Chief Engineer of Mysore

GPB—6,000—21-7-06

~~the words.~~ , as well as to the Dy Comr

2. The Enclosures are here with

ret'd

RO

DFK 9/1/07
Secretary

9/1/07

Ans

Received 4283 1907

Regd

18/3/07

~~Enclosure~~

Regd

19/3/07

~~189~~ 1906-07

From ... Esq: B.A.

Deputy ... Commissioner

& Magistrate ... District

To

... Secretary to the Govt: of ... B.A.

...

Dated 16th ... 1907.

Despatched

Received

General No. 379

No.

Enclosure No. 2

... Copy of ... letter ...

... forwarding ... number of ...

... Certificates granted ...

Emigrant labourers ... during ...

... January ...

Deputy Commissioner's Office
Mysore District
Dated Mysore 16th March 07

No 379
Ann 2

To

L. Anantasami Rao Esq B.A.
Secretary to [illegible]

Sir,

Adverting to [illegible] of
-ceedings No 2288-90 dated 11th
December 1906 sanctioning an esti-
-mate for Rs 570/- for the replacement
of the Dhwajasthan shed in the temple
of the Sri Srikanteswara Swami at
Nanjangud, I have the honour to
that the Sub Divisional officer,
jangud, [illegible]
a copy of [illegible]
received from the Executive [illegible]
-ers, [illegible], informing
that no single tree [illegible] of 4½
feet [illegible]
Mysore forests and that the wood
cannot be had [illegible]
pole [illegible]
as to [illegible] be done in the
matter under the circumstances
adding that [illegible]
officers of [illegible]

Should be 46 ft. long. very sacred

Banni Mara
Honne Mara
Sampige Mara
Hippe Mara

These are not strong. long and thick poles cannot be found.

Géru
Devadaru
Panne Mara
Gandhada Mara
Adike Mara
Chowkekayi Mara
Bombu
Muthuga
Bilva Vrikkoha

Impossible required length

2. [illegible]

-ally [illegible]

3. [illegible]

-ne, Sampige [illegible]

46 feet [illegible]

to be very sacred ones for Dhwa

-jastambha. [illegible]

poles of the [illegible]

reported to be rare and not

strong.

4. In the absence of [illegible]

I solicit instructions [illegible]

matter of utilizing for the Dhwa-

-jastambha [illegible]

wood referred to [illegible]

if available.

5. The Sub Divisional Officer's letter

No. 1135 dated 6.3.1907 is herewith

submitted for reference.

I have the honor to be,

Sir,

your most obedient servant

Deputy Commissioner

Bellary District.

1907

From The
Assistant Engineer
Nanjangud Range

To The Amildar
Nanjangud

Dated 3-3-07

General No 79

Thwaja Stambha of
Srikanteswara Swami
Temple at Nanjangud

I report that no Single
Sonne pole of 46½ in
length can be procured in the
Mysore forests.

The work

Cannot be done unless such a pole can be formed

(SO) B. C. Srinivasa Iyengar.
Assistant Engineer
Nanjangud Range

No 4986 Ent
D/2514/07

2.

The Dy Commr
Anjaum District

Sir,

With reference to your letter no 379 dated 16th March 1907 soliciting instructions in the matter of issuing for Shunjeshwar Swami Temple at Nanjangud, I am directed to forward herewith a copy of this Office Agraharik's memo dated 23rd March 1907, from

from which it will be
seen that Hippa, Humma,
Sarpinga and Sama
are the best ones for
Dhanjashankha —

2. As it is reported that a
Humma pole of 46½ feet
in length is not available,
one of the other 3 kinds
viz Hippa, Sarpinga and
Sama may be secured
for the purpose —

I have &c

21/4/07
Engineer-in-Chief

21/4/07

7/4/07

No. 4987

Copy to the Chief Engineer
in continuation of Govt
Pro: Mog. No. 1208-90 dated
24th Dec. 1906.

By Order

21/4/07

Office copy

ಸ್ವಲ್ಪ ಹೊತ್ತು ಮಾತ್ರ ಸ್ವಲ್ಪ ಸಾಲ್ಗಳು ಮಾತ್ರ ಬಿಡದೆ ಬಳಲಿಕೆಯಾಗಿ
ಇದ್ದು ಸಂಜೆ ಆಗುವಷ್ಟರಲ್ಲಿ ಕೆಲಸ ಮುಗಿದಿರುತ್ತದೆ.

ಶ್ರೀ 23-3-07 ಇಲ್ಲಿಗೆ ಸಂಬಂಧಪಟ್ಟ ರಂಗಕಲೆಯ ಸಂಭಾಷಣೆ ಪೂರ್ಣಗೊಂಡಿದೆ.